



**01 July 2004**

**Question:**

**Std: NZS 4541:2003**

**Std: NZS 4510**

Do fire sprinkler and hydrant inlets need to be tested in compliance with clause 107.3 (NZS 4541) and clause 9.1.1 (b) (NZS 4510)?

**Interpretation:**

**Issued by the Fixed Fire Protection Group**

Yes.

*Comment: It is noted that the only practical option to prove the integrity of an fire sprinkler and hydrant inlets is a pressure test and the other options provided in 107.3 NZS 4541 should not be permitted.*

**Reviewed in 2008 and deemed not applicable to NZS 4541:2007  
(applies to 2003 edition)**

**FI 017**